

Inspection Photos

April 4, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 421223

Location Name: McLin A Pad

Inspection Document #: 702800110

Garfield County, CO

SESW Section 12 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 1. Photo taken from the Location entrance facing north shows an overview of the Location. Photo also shows areas no longer in use have not been reclaimed per 1003 Rules.

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



4/4/22
+39.537375,-107.616776

Photo 2. Photo taken from the northeast of the Location facing south shows areas no longer in use have not been reclaimed per 1003 Rules.

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 3. Photo taken from the west of the Location shows undesirable plant species/weed debris accumulating on Location.



Photo 4. Photo taken from the east of the Location shows skeletons from the undesirable plant species/weed, kochia in the middleground and seedlings in the foreground.

Inspection Number: 702800110



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 5. Photo taken from the west of the Location facing south shows the slopes of the Location are colonized by annual, invasive, undesirable plant species/weeds including purple mustard, cheatgrass and kochia.



Photo 6. Photo taken from the northwest of the Location facing northeast. Refer to additional comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800110

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 7. Photo taken from the east of the Location facing north shows the slopes of the Location are colonized by annual, invasive, undesirable plant species/weeds including purple mustard, cheatgrass and kochia.



Photo 8. Photo taken from the southeast of the Location facing east. Refer to additional comments under Photo 7.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800110