

Inspection Photos
Operator: Logos
API: 067-08135
Date: 4/5/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing here with western wheatgrass, sand dropseed, and crested wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of reclaimed grass field with western wheatgrass, sand dropseed, crested wheatgrass, and fourwing saltbush.