

Inspection Photos
Location Name: Wilson Creek 18
Location ID: 314515



Photo 1. Overview of location taken facing west.



Photo 2. Tubing stored on location.