

Inspection Photos
Location Name: Standley 1-2, 2-2
Location ID: 320511



Photo 1: Wellhead Sign



Photo 2: Stained soil



Inspection Photos
Location Name: Standley 1-2, 2-2
Location ID: 320511



Photo 3: Wellhead Sign



Photo 4: Stained soil



Inspection Photos
Location Name: Standley 1-2, 2-2
Location ID: 320511



Photo 5: Unused/disconnected equipment



Photo 6: Temporary tank removed

Inspection Photos
Location Name: Standley 1-2, 2-2
Location ID: 320511



Colorado Oil & Gas Conservation Commission
40.00008, -104.96143, 1536.8m, 93°
Apr 8, 2022 11:03:10 AM

Photo 7: Tank Battery