

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NENW

Location ID: 311566



Photo #6381 from entrance to location.



Photo #6382 Loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NENW

Location ID: 311566



Photo #6383 Multiple places with trash located on location.



Photo #6384 Multiple places with trash located on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NENW

Location ID: 311566



Photo #6383 Multiple places with trash located on location.