

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal /SG 43-28

Location ID: 334978



Photo #6388 from entrance to location.



Photo #6389 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal /SG 43-28

Location ID: 334978



Photo #6392 No battery sign Located at the tank battery.



Photo #6393 Loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal /SG 43-28

Location ID: 334978



Photo #6390 Location lacks stabilization.



Photo #6391 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal /SG 43-28

Location ID: 334978



Photo #6395 Insufficient tracking control at entrance to location.