

Inspection Photos

API: 071-06704

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06704 | Date: 4/4/2022

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06704 | Date: 4/4/2022

Inspection Photos



Photo 2. The well sign is posted at meter shed. The cut slope is stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06704 | Date: 4/4/2022

Inspection Photos



Photo 3. There is an unused and degraded shed at the location that needs to be removed. The tin roof is coming apart and piece of tin on ground needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06704 | Date: 4/4/2022