

Inspection Photos

API: 071-06703

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06703 | Date: 4/4/2022

Inspection Photos



Photo 1. Facing northeast along the main road. Additional gravel has been applied to the road for stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06703 | Date: 4/4/2022

Inspection Photos



Photo 2. The area of erosion previously observed has been repaired, seeded, and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06703 | Date: 4/4/2022

Inspection Photos



Photo 3. Facing northeast toward the wellsite.

