

Inspection Photos

API: 071-08868

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08868 | Date: 4/4/2022

Inspection Photos



Photo 1. Facing southwest along the main road traveling to the location. There are areas of vehicle rutting. The road will need to be graded and maintained and areas may need additional stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08868 | Date: 4/4/2022

Inspection Photos



Photo 2. Facing southeast toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08868 | Date: 4/4/2022

Inspection Photos



Photo 3. Facing southwest toward the wellsite.



Inspection Photos



Photo 4. Facing west toward the interim reclamation area. This area is stabilized with vegetation. There is a camper trailer stored on location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08868 | Date: 4/4/2022