

# Inspection Photos

API: 071-06720

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06720 | Date: 4/4/2022

## Inspection Photos



**Photo 1.** Facing south toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06720 | Date: 4/4/2022



## Inspection Photos



**Photo 2.** There is oily fluid in the engine skid which is spilling onto the ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06720 | Date: 4/4/2022