

# Inspection Photos

API: 071-07239

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07239 | Date: 4/4/2022

## Inspection Photos



**Photo 1.** Facing north along the main road traveling to the location. There are areas of vehicle rutting. The road will need to be graded and maintained and areas may need additional stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07239 | Date: 4/4/2022

## Inspection Photos



**Photo 2.** Facing northwest along the main road near the location. There are areas of vehicle rutting. The road will need to be graded and maintained and areas may need additional stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07239 | Date: 4/4/2022

## Inspection Photos



**Photo 3.** Facing southwest toward the location.



## Inspection Photos



**Photo 4.** There last years growth of noxious weeds (Canada thistle). Noxious weeds should be monitored and controlled during upcoming growing season.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07239 | Date: 4/4/2022

## Inspection Photos



**Photo 5.** Facing toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07239 | Date: 4/4/2022

## Inspection Photos



**Photo 6.** Well sign posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07239 | Date: 4/4/2022