

# Inspection Photos

API: 071-09651

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09651 | Date: 4/4/2022

## Inspection Photos



**Photo 1.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09651 | Date: 4/4/2022

## Inspection Photos



**Photo 2.** The pipe riser near the location and adjacent to the main road is LO and labeled as active line.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09651 | Date: 4/4/2022

## Inspection Photos



**Photo 3.** Facing northeast at the location. The perennial vegetation has uniformly re-established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09651 | Date: 4/4/2022

## Inspection Photos



**Photo 4.** Facing east toward the cut slope which is stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09651 | Date: 4/4/2022

## Inspection Photos



**Photo 5.** Facing east toward the fill slope which is stabilized.



## Inspection Photos



**Photo 6.** A shallow pit remains at the location and was never used for production. Pit remains per approved variance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09651 | Date: 4/4/2022

## Inspection Photos



**Photo 7.** Facing west at the location. The perennial vegetation has uniformly re-established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09651 | Date: 4/4/2022