

# Inspection Photos

April 04, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 419675

Location Name: Jolley /KP 13-17

Inspection Document #: 702800120

Garfield County, CO

NWSW Section 17 T6S R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Jolley /KP 13-17  
Location ID: 419675

4/4/22  
+39.525540,-107.586630



**Photo 1.** Photo taken from the Location entrance facing northwest shows an overview of the Location and the lack of signage at the Location entrance.

Inspection Photos  
Location Name: Jolley /KP 13-17  
Location ID: 419675



**Photo 2.** Photo taken from the southeast of the Location facing northeast shows storage of a trailer on Location. Photo also shows a lack of stabilization BMPs as is evidence by the presence of ruts.



Inspection Photos  
Location Name: Jolley /KP 13-17  
Location ID: 419675



**Photo 3.** Photo taken from the south of the Location facing west shows slopes colonized by perennial grasses and annual undesirable plant species/weeds.



**Photo 4.** Photo taken from the southwest of the Location facing northwest. Refer to additional Photo 3 comments.



Inspection Photos  
Location Name: Jolley /KP 13-17  
Location ID: 419675



**Photo 5.** Photo taken from the west of the Location facing north shows a soil stockpile dominated by annual undesirable plant species/weeds and sparse perennial grasses.





Inspection Photos  
Location Name: Jolley /KP 13-17  
Location ID: 419675



**Photo 6.** Photo taken from the east of the Location facing south shows an overview of the eroding cut slope.



**Photo 7.** Photo taken from the east of the Location shows rill erosion occurring on the cut slope.



Inspection Photos  
Location Name: Jolley /KP 13-17  
Location ID: 419675



**Photo 8.** Photo taken from the east of the Location facing east shows undercutting and lateral erosion of cut slopes resulting in exposed roots and vegetation and soil loss from native plants communities off-Location.



**Photo 9.** Refer to Photo 8 comment. A straw wattle does not appear to sufficiently prevent erosion.

Inspection Number: 702800120