

Inspection Photos

API: 071-08460

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08460 | Date: 4/4/2022

Inspection Photos



Photo 1. Facing east toward the wellsite. The location is stabilized and vegetation is well established along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08460 | Date: 4/4/2022

Inspection Photos



Photo 2. The well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08460 | Date: 4/4/2022