

# Inspection Photos

API: 071-06838

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/4/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06838 | Date: 4/4/2022

## Inspection Photos



**Photo 1.** Facing east at the beginning of the access road. There is erosion channels along this area of the road that need to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06838 | Date: 4/4/2022

## Inspection Photos



**Photo 2.** There is signs that stormwater has eroded over the water bar shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06838 | Date: 4/4/2022

## Inspection Photos



**Photo 3.** Facing southeast along the access road. The remainder of the road appeared to be stabilized and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06838 | Date: 4/4/2022

## Inspection Photos



**Photo 4.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06838 | Date: 4/4/2022

## Inspection Photos



**Photo 5.** Facing toward the fill slope of the location. There is a small shed at the southern edge of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06838 | Date: 4/4/2022

## Inspection Photos



**Photo 6.** Facing toward the cut slope which is stabilized with perennial vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06838 | Date: 4/4/2022

## Inspection Photos



**Photo 7.** Facing toward the cut slope which is stabilized with perennial vegetation.

