

# Inspection Photos

API: 055-06306

Operator: MANZANO LLC

Inspection Date: 4/6/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 4/6/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing northwest toward the access road and the location. Red arrow points the the access road and yellow arrow points to the location which have not been reclaimed per rule 1004. Photo taken on 10/5/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 4/6/2022

## Inspection Photos



**Photo 2.** Drone aerial photo facing toward the access road which crossing the perennial stream. The culvert has become exposed due to erosion and is susceptible to further erosion.



**Photo 3.** The culvert has become exposed due to erosion and is susceptible to further erosion and potential washout.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 4/6/2022

## Inspection Photos



**Photo 4.** Facing toward the access road which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 4/6/2022

## Inspection Photos



**Photo 5.** Facing northwest overlooking the location disturbance which is approximately 2.3 acres in size. Aerial image of the location shows the location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 4/6/2022

## Inspection Photos



**Photo 6.** Facing northwest along the fill slope. There are numerous noxious weeds still remain along the fill slope. Noxious weeds observed include: Common mullien, Musk thistle, Plumeless thistle, and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 4/6/2022

## Inspection Photos



**Photo 7.** Facing south overlooking the location disturbance which is approximately 2.3 acres in size. The location has not been recontoured and reclaimed and is mostly bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 4/6/2022