

Inspection Photos

API: 055-06154

Operator: PETROGLYPH OPERATING CO

Inspection Date: 4/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06154 | Date: 4/6/2022

Inspection Photos



Photo 1. Facing east along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 4/6/2022

Inspection Photos



Photo 2. Center of the location facing north. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 4/6/2022

Inspection Photos



Photo 3. Center of the location facing west. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 4/6/2022

Inspection Photos



Photo 4. Center of the location facing south. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 4/6/2022

Inspection Photos



Photo 5. Center of the location facing east. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 4/6/2022

Inspection Photos



Photo 6. Drone aerial photo facing southeast toward reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06154 | Date: 4/6/2022