

Caerus Piceance LLC  
D17E  
Location # 324060



**Location/ lack of battery signage**



**location**





Caerus Piceance LLC  
D17E  
Location # 324060



Location



Debris





Caerus Piceance LLC  
D17E  
Location # 324060



Sink holes/ erosion



Sink holes/ erosion





Caerus Piceance LLC  
D17E  
Location # 324060



**Sink holes/ erosion**



**Sink holes/ erosion**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources