

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2022

Submitted Date:

04/12/2022

Document Number:

699105206

FIELD INSPECTION FORM

Loc ID 331481 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262518	WELL	TA	04/06/2021	GW	123-20752	LF RANCH 17-31	TA

General Comment:

[This is a follow up to FIRR #403006396. CA has been corrected.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 262518 Type: WELL API Number: 123-20752 Status: TA Insp. Status: TA**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 06/28/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 4/8/22 at approximately 1142hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #403006396 at LF Ranch 17-31 of Noble Energy, at Location ID# 331481 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules. See attached photos. This is a summary of inspection report.</p>	burnsa	04/12/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105207	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721072