

Inspection Photos
Location Name: Koseter 3-33-3 Pad
Location ID: 302685



Production facility




Wellheads

Inspection Photos
Location Name: Koseter 3-33-3 Pad
Location ID: 302685



Wellhead



Master valve leak and stained soil

Inspection Photos
Location Name: Koseter 3-33-3 Pad
Location ID: 302685



Wellhead



Master valve leak and stained soil