

Inspection Photos
Location Name: R&G #26-2
API: 05-067-08671



Stained gravel around #26-3 well head.



Stained gravel around #26-2 well head.

Inspection Photos
Location Name: R&G #26-2
API: 05-067-08671



Tank labels are peeling off of tanks and are not compliant with Rule 605.h.



Tanks have been inspected by the operator and standing water inside of containment is reported to be storm water.