

Inspection Photos
Location Name: State 16-7-60-1H
Location ID: 432352




Photo 1 – Tank Battery Sign



Photo 2 – Tank Battery



Inspection Photos
Location Name: State 16-7-60-1H
Location ID: 432352



Photo 3 – Netting in Disrepair



Photo 4 – Stained Soil



Inspection Photos
Location Name: State 16-7-60-1H
Location ID: 432352




Photo 5 – Stained Soil



Photo 6 – Stained Soil

Inspection Photos
Location Name: State 16-7-60-1H
Location ID: 432352



Photo 7 – Wellhead



Photo 8 – ECD and Flare

Inspection Photos
Location Name: State 16-7-60-1H
Location ID: 432352



Photo 9 – Missing Wildlife Netting



Photo 10 – Heater Treater, Compressor and Gas Meter



Inspection Photos
Location Name: State 16-7-60-1H
Location ID: 432352



Photo 11 – Missing Wildlife Netting

