

Inspection Photos
Location Name: Behring 23-7 Tank Battery
Location ID: 332096



Photo 1 – Tank Battery Sign



Photo 2 – Tank Battery



Inspection Photos
Location Name: Behring 23-7 Tank Battery
Location ID: 332096




Photo 3 – Unmarked Risers at the backs of the Tanks



Photo 4 – Heater Treater



Inspection Photos
Location Name: Behring 23-7 Tank Battery
Location ID: 332096



Photo 5 – Pit Area