

Inspection Photos
Location Name: Babb 14-14
Location ID: 332405



Photo 1 – Tank Battery Sign



Photo 2 – Tank Battery



Inspection Photos
Location Name: Babb 14-14
Location ID: 332405




Photo 3 – Unmarked Risers at the backs of the Tanks



Photo 4 – Heater Treater and ECDs

Inspection Photos
Location Name: Babb 14-14
Location ID: 332405



Photo 5 – Wellhead



Photo 6 – Pumping Units



Inspection Photos
Location Name: Babb 14-14
Location ID: 332405



Photo 7 – Wellhead Signs



Photo 8 – Pit

