

Inspection Photos
Location Name: Castor 7-59-12-1-1
Location ID: 465272



Photo 1 - Wellhead – Stained Soil




Photo 2 – Oily Waste at Wellhead



Inspection Photos
Location Name: Castor 7-59-12-1-1
Location ID: 465272



Photo 3 – Unused Hoses and Containments



Photo 4 – Trash/Unused Parts

Inspection Photos
Location Name: Castor 7-59-12-1-1
Location ID: 465272



Photo 5 – Separators



Photo 6 – Compressor, VRU and Gas Meters

Inspection Photos
Location Name: Castor 7-59-12-1-1
Location ID: 465272



Photo 7 – ECD



Photo 8 – Tank Battery – Oil Tanks

Inspection Photos
Location Name: Castor 7-59-12-1-1
Location ID: 465272



Photo 9 – Tank Battery Signs



Photo 10 – Tank Battery – Water Tanks

