

Inspection Photos  
Location Name: Bangert 42-19  
Location ID: 317922



Photo 1 WH sign.

Photo 2 WH

**Inspection Photos**  
**Location Name: Bangert 42-19**  
**Location ID: 317922**



**Photo 3 ancillary equip.**

**Photo 4 pump jack**



Inspection Photos  
Location Name: Bangert 42-19  
Location ID: 317922



Photo 5 TB sign

Photo 6 TB



Inspection Photos  
Location Name: Bangert 42-19  
Location ID: 317922



Photo 7 Horiz. Heated Sep.

Photo 8 Gas Meter Run