

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #6423 from entrance to location.



Photo #6424 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #6425 Location lacks stabilization.



Photo #5299 from inspection #699804135 conducted on 2/11/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #6426 Location lacks stabilization.



Phot #5925 From inspection #699804135 conducted on 2/11/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #6427 Insufficient tracking BMP located at the entrance to location.