

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



Photo #6424 from entrance to location.



Photo #6425 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



Photo #6430 Loadline open ended.



Photo #6431 Vent pipe on tank open ended.