


Caerus Piceance LLC
I13
Location # 334665



Location/ lack of battery signage



location

Caerus Piceance LLC
I13
Location # 334665



Location



Lack of stabilization/compaction

Caerus Piceance LLC
I13
Location # 334665



Lack of stabilization/compaction



Lack of stabilization/compaction

Caerus Piceance LLC
I13
Location # 334665



Open pipe



Valve missing cap/plug