

Caerus Piceance LLC
P13W
Location # 334576



Location/lack of battery signage



location



Caerus Piceance LLC
P13W
Location # 334576



Location



Lack of stabilization/compaction



**Caerus Piceance LLC
P13W
Location # 334576**



Lack of stabilization/compaction



Valve missing cap/plug



Caerus Piceance LLC
P13W
Location # 334576



Sediment pushed over berm



Sediment pushed over berm



Caerus Piceance LLC
P13W
Location # 334576



Sediment pushed over berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources