

Caerus Piceance LLC
F24W
Location # 334693



Location/ lack of battery signage



location



Caerus Piceance LLC
F24W
Location # 334693



Location



location

Caerus Piceance LLC
F24W
Location # 334693



Open pipe



Lack of plug/cap

Caerus Piceance LLC
F24W
Location # 334693



Debris



Lack of stabilization/compaction

Caerus Piceance LLC
F24W
Location # 334693



Lack of stabilization/compaction



Lack of stabilization/compaction

