

Caerus Piceance LLC
H23W
Location # 334679



Location



location/ lack of battery signage

Caerus Piceance LLC
H23W
Location # 334679



Location



Lack of plug/cap

Caerus Piceance LLC
H23W
Location # 334679



Open pipe



Lack of stabilization/compaction



Caerus Piceance LLC
H23W
Location # 334679



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
H23W
Location # 334679



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
H23W
Location # 334679



Lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources