

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /5NWNW

Location ID: 334725



Photo #6460 from entrance to location.



Photo #6461 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /5NWNW

Location ID: 334725



Photo #6462 Location lacks stabilization.




Photo #6463 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /5NWNW

Location ID: 334725



Photo #6464 Insufficient tracking BMP at entrance to location.