



Photo Illustrations of Remediation Investigation

Page 1 of 8

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)



Site Overview - East Orientation



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 2 of 8



Excavation Overview - North Orientation



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 3 of 8



Excavation Area - View Northeast



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 4 of 8



Point of Release - View East



Photo Illustrations of Remediation Investigation

Page 5 of 8

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)



West Pothole - View East



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)



South Pothole - View Northeast



Photo Illustrations of Remediation Investigation

Page 7 of 8

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)



East Pothole - View Northeast



Photo Illustrations of Remediation Investigation

Page 8 of 8

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)



North Sidewall - View North