



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 1 of 10



Site Overview: East Orientation



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 2 of 10



Excavation: View Northwest



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 3 of 10



Excavation: View South



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 4 of 10



Excavation: View Northeast



Photo Illustrations of Remediation Investigation

Page 5 of 10

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)



Northern Pothole Location: View Northwest



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 6 of 10



SSW@8', WSW@8', and BASE@10' Sample Locations: View Southeast



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 7 of 10



ESW@7' Sample Location: View Northeast



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 8 of 10



BGW1@2': View North



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 9 of 10



BGW2@1': View Northeast



Photo Illustrations of Remediation Investigation

Remediation Investigation
SGV 7N (COGCC Location ID: 334127)

Page 10 of 10



BGW Samples 3-5 Collection Area: View Southwest