

Location Name: Lowe #3-12, #8-12 Location ID/API #: 461219



Stained soil inside containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Lowe #3-12, #8-12 Location ID/API #: 461219



4/14/22 10:55
38.68216N 102.41128W

Location Name: Lowe #3-12, #8-12 Location ID/API #: 461219



Location Name: Lowe #3-12, #8-12 Location ID/API #: 461219



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not OOSLAT (out of service locks and tags).

Location Name: Lowe #3-12, #8-12 Location ID/API #: 461219



4/14/22 10:56
38.68221N 102.41110W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not OOSLAT (out of service locks and tags).

Location Name: Lowe #3-12, #8-12 Location ID/API #: 461219

