



**Inspected Facilities**

Facility ID: 471599 Type: OFF- API Number: - Status: AC Insp. Status: EI

## Environmental

**Spill/Remediation:**

Comment: COGCC Inspection production facility decommissioning, Remediation Project 21178. All facilities have been removed, except meter shed. Operator will submit results of soil sampling and laboratory analysis on Form 27 Supplemental.

Corrective Action: Submit results of soil sampling and laboratory analysis on Form 27 Supplemental by June 30, 2022. Date: 06/30/2022

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403013244	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721822</a>
693700932	Production Facility viewing north	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721806">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721806</a>
693700933	Production Facility viewing south	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721807">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721807</a>