

WELL SITE INSPECTION FORM



Well Name ELIFF 1-1 API Number 05 -
 Operator BERENERGY Permit #
 Location S WNE1-9N-53W County LOGAN
 Field PADRONA WEST Inspector R. Van Sickle
 AL/PA/DA Inspection Results: Well Status:
 Pass(Y) Fail(N) Date FN FD WO PR SI ✓

=====

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
 Consistent with APD casing Program? YES NO Returns
 Rig BOP'S Contact

Date of Inspection Before/During/After Completion 4-18-96

Prod. Csg. Set? ✓ Completion Rig/Activity
 Drilling Pits: Closed ✓ Open Wellhead Installed Y ✓ N
 Tank ID: Yes ✓ No N/A Skim Tank/Pit: Prod. Tanks: (2) 300 BBLs
 Equipment FV-11T Meter Run: Yes ✓ No ✓
 Bradenhead Press: Fluid: No Yes Type Well Cat.

AL/PA/DA Inspection

Date Plugged: Date Permit Expired:
 Hole Plugged: Yes No Pits Backfilled: Yes No
 Material Buried: Yes No N/A Site Clean: Yes No
 Bond Release OK: Yes No Fed Hole Marker: Yes No

Date of Safety/Status Inspection

Comments: 75' x 125' PIT IS THERE & HAS BEEN FOR SOME TIME.
STOCK WATER WELL ± 600' EAST.

Violations: Yes No ✓ Notice Sent: Yes No Date Sent: