

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 1 - Wellhead – Stained Soil

Photo 2 – Wellhead – Tubing Valves appear to be Closed Position

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 3 – Wellhead



Photo 4 – Heater Treater

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 5 – Unused Cat Walk

Photo 6 – Fence in disrepair

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 7 – Tank Battery



Photo 8 – West Tank missing Labels

Inspection Photos
Location Name: USA 21-6
Location ID: 318871



Photo 9 – Unused Valve at Tanks