

Inspection Photos
Location Name: Susan #1
Location ID: 323754



Photo 1: Wellhead Sign



Photo 2: Wellhead



Inspection Photos
Location Name: Susan #1
Location ID: 323754



Photo 3: Tank Battery Sign



Photo 4: Tank Battery

Inspection Photos
Location Name: Susan #1
Location ID: 323754



Photo 5: Equipment




Photo 6: Gas meter not annually calibrated