

Inspection Photos
Location Name: Stroh N 35-10
Location ID: 323557



Photo 1: Wellhead Sign




Photo 2: Wellhead



Inspection Photos
Location Name: Stroh N 35-10
Location ID: 323557




Photo 3: Tank Battery Sign



Photo 4: Centralized Tank Battery



Inspection Photos
Location Name: Stroh N 35-10
Location ID: 323557



Photo 5: Equipment



Photo 6: Gas meter not annually calibrated