

Inspection Photos

April 18, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334935

Location Name: Boulton-66S92W 33SWNE

Inspection Document #: 702800128

Garfield County, CO

SWNE Section 33 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Boulton-66S92W 33SWNE
Location ID: 334935



Photo 1. Photo taken from the southwest of the Location facing northeast shows an overview of the Location.



Inspection Photos
Location Name: Boulton-66S92W 33SWNE
Location ID: 334935



Photo 2. Photo taken from the tank battery shows the label on a methanol tank in disrepair.



Photo 3. Photo taken from the north of the Location facing southwest shows an unmarked anchor.

Inspection Photos
Location Name: Boulton-66S92W 33SWNE
Location ID: 334935



Photo 4. Photo taken from the southeast of the wells facing north shows where previously unmarked anchors appear to have been removed.



Inspection Photos
Location Name: Boulton-66S92W 33SWNE
Location ID: 334935



Photo 5. Photo taken from the southwest of the Location facing south shows slopes colonized by perennial grasses.



Photo 6. Photo taken from the south of the Location facing northeast shows interim areas colonized by perennial grasses.



Inspection Photos
Location Name: Boulton-66S92W 33SWNE
Location ID: 334935



Photo 7. Photo taken from the east of the Location facing south shows interim areas colonized by rubber rabbitbrush. Photo also shows gravel remaining in the interim area.



Photo 8. Photo taken from the north of the Location facing west shows a slope colonized by perennial grasses and CO List B noxious weeds cheatgrass and bulbous bluegrass.