

Inspection Photos

April 18, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334927

Location Name: Couey-67S92W /5SESW

Inspection Document #: 702800132

Garfield County, CO

SESW Section 5 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Couey-67S92W /5SESW
Location ID: 334927



Photo 1. Photo shows revegetation progress on the Location.



Photo 2. Refer to Photo 1 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800132

Inspection Photos
Location Name: Couey-67S92W /5SESW
Location ID: 334927



Photo 3. Photo shows revegetation progress on the Location.



Photo 4. Refer to Photo 3 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800132

Inspection Photos
Location Name: Couey-67S92W /5SESW
Location ID: 334927



Photo 5. Photo taken from the southeast of the Location facing north shows a straw wattle on the perimeter of the Location.



Photo 6. Photo taken from the northeast of the Location facing west shows a straw wattle on the perimeter of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800132