

# Inspection Photos

API: 071-08082

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08082 | Date: 4/19/2022

## Inspection Photos



**Photo 1.** Facing northeast along the main road . There is a pile of cement debris that needs to be removed. This area of disturbance needs to be reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08082 | Date: 4/19/2022

## Inspection Photos



**Photo 2.** Facing east toward the access road stream crossing. The road side area was repaired and rock check dams were installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08082 | Date: 4/19/2022

## Inspection Photos



**Photo 3.** Facing southwest toward the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08082 | Date: 4/19/2022

## Inspection Photos



**Photo 4.** Facing southwest toward the access road. This area of erosion has not been repaired and stabilized. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08082 | Date: 4/19/2022

## Inspection Photos



**Photo 5.** Further up the access road. There is stormwater erosion across the road. This area needs a culvert to prevent stormwater from eroding across the road and also further down the road side shown in previous photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08082 | Date: 4/19/2022

## Inspection Photos



**Photo 6.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08082 | Date: 4/19/2022