

# Inspection Photos

April 18, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334963

Location Name: Couey-67S92W /5SESW

Inspection Document #: 702800134

Garfield County, CO

SESW Section 5 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Couey-67S92W /5SESW  
Location ID: 334963



**Photo 1.** Photo taken from the Location entrance facing northwest shows an overview of the Location.



**Photo 2.** Photo taken from the Location entrance facing southwest shows an overview of the Location.





Inspection Photos  
Location Name: Couey-67S92W /5SESW  
Location ID: 334963



**Photo 3.** Photo taken from the southeast of the Location facing south shows interim areas colonized by sparse perennial grasses, curlycup gumweed, rubber rabbitbrush and sagebrush.



**Photo 4.** Photo taken from the west of the Location facing north shows interim areas colonized by sparse perennial grasses, rubber rabbitbrush and annual invasive weeds/undesirable plant species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800134



Inspection Photos  
Location Name: Couey-67S92W /5SESW  
Location ID: 334963



**Photo 5.** Photo taken from the west of the Location facing north shows the western interim area dominated by annual invasive weeds/undesirable plant species including pale madwort, cheatgrass, bur buttercup and Russian thistle, with minimal perennial grasses.



**Photo 6.** Photo taken from the west of the Location facing south shows contrasting perennial establishment, with perennial grasses established in the foreground and a lack of establishment in the middleground.