

Inspection Photos

April 18, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 335361

Location Name: Brynildson-66S92W /29NENW

Inspection Document #: 702800141

Garfield County, CO

NENW Section 29 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brynildson-66S92W /29NENW
Location ID: 335361



Photo 1. Photo taken from the Location entrance facing north shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800141

Inspection Photos
Location Name: Brynildson-66S92W /29NENW
Location ID: 335361



Photo 2. Photo taken from the south of the Location facing west shows the slopes of the access road appear stable, but are largely unvegetated.



Photo 3. Photo taken from the south of the Location facing north shows interim areas colonized by sparse perennial grasses, forbs and shrubs and annual invasive/undesirable plant species/weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800141

Inspection Photos
Location Name: Brynildson-66S92W /29NENW
Location ID: 335361



Photo 4. Photo taken from the northwest of the Location facing south shows the western interim area is dominated by perennial grasses, with annual invasive/undesirable plant species/weeds also present.



Photo 5. Photo taken from the north of the Location facing west shows the northern interim area is colonized by perennial grasses, with a high amount of annual invasive/undesirable plant species/weeds also present.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800141