

Inspection Photos
Location Name: Perry 3
Location ID: 318935



Pic 1 wellhead



Pic 2 gas meter run

Inspection Photos
Location Name: Perry 3
Location ID: 318935



Pic 3 separator




Pic 4 tanks

Inspection Photos
Location Name: Perry 3
Location ID: 318935



Pic 5 mechanical issue with grease zerk, stained soil.



Pic 6 mechanical issue with grease zerk, stained soil