

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



**Photo #6470 from entrance to location.**

**Photo #6471 from entrance to location.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



Photo #6472 No battery sign located at the tank battery.



Photo #5603 from inspection #699803973 conducted on 1/6/22.