

Construction and Stormwater Inspection

April 8, 2022

Operator: MORNING GUN EXPLORATION LLC #10656

Location ID: 465272

Inspection Document #: 697503871

Weld County, CO

SWSE Section 12 T7N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Castor 7-59 /12
Location ID: 465272



Photo 1. Drone aerial imagery illustrates the northern Castor location. Photo illustrates the Operator has stabilized the location was roadbase.

Inspection Photos
Location Name: Castor 7-59 /12
Location ID: 465272



Photo 2. Drone aerial imagery illustrates the eastern Castor location. See comments under Photo 1.



Photo 3. Drone aerial imagery illustrates the southern Castor location. See comments under Photo 1.

Inspection Photos
Location Name: Castor 7-59 /12
Location ID: 465272



Photo 4. Drone aerial imagery illustrates the western Castor location. See comments under Photo 1.