

# Inspection Photos

API: 071-09475

Operator: OGRIS OPERATING LLC

Inspection Date: 4/29/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/29/2022

## Inspection Photos



**Photo 1.** The road was closed due to work being performed at time of inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/29/2022

## Inspection Photos



**Photo 2.** There was an excavator which appear to be addressing the previous corrective action related to stormwater issues.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/29/2022

## Inspection Photos



**Photo 3.** This is some of the issues observed during the last inspection. Facing west along the main road at Lat/Long:37.1099,-104.94878. Erosion has occurred along the fill slope of the road. This area needs to be repaired and stabilized. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/29/2022

## Inspection Photos



**Photo 4.** There was a new culvert installed near the location where frequent stormwater issues was observed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/29/2022

## Inspection Photos



**Photo 5.** Facing toward the wellsite. The fence around the pit was repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/29/2022

## Inspection Photos



**Photo 6.** There was a dripping leak coming from inside the meter shed. Operator was notified by phone call.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/29/2022